

Power Monitor MultiPower metering system for **AC** applications



CUTOUTS, DIMENSIONS AND CONNECTIONS



Meter Dimensions (in mm)



Wiring Connections

= faces Source

= X2 (black) = Grounded



1ph 3W

3ph 3W 3ph 4W 3ph 3W BA

2 SOURCE

Unused voltage terminals are internally connected. Secondary of CTs must be connected to ground/earth.



k = X1 (white)



